USEPA 290 BROADWAY

NY, NY NOTIFICATION OF DEMOLITION AND RENOVATION PAL JOB # 16-1227

Operator Project #	Postmark	Date Rec	eived	Notification #					
TYPE OF NOTIFICATION (O-Original, R-Received, C-Cancelled): R – New Start Date									
FACILITY INFORMATION (Identify Owner, Removal Contractor and Other Operator):									
OWNER NAME: Riverbay Corporation									
Address: 2049 Bartow Avenue									
City: Bronx State: NY Zip: 10475									
Contact Name: Noel Ellison	Tolonh	Telephone: 718-320-3300							
REMOVAL CONTRACTOR: PAL Environmental Safety Corp. d/b/a PAL Environmental Services									
Address: 11-02 Queens Plaza	South	p. u/b/a FAL	LITVII OTITIE	iliai Services					
City: Long Island City			State: NY			7: 11101			
Contact Name: Aric Domozick				Telephone: 718-349-0900			Zip: 11101		
OTHER CONTRACTOR:									
Address:									
City:				Ctata			7:		
Contact Name:	T Course								
TYPE OF OPERATION (D-Demo, O-Ordered Demo, R-Renovation, E-Emergency Renovation: R									
IS ASBESTOS PRESENT? (YES NO) YES									
FACILITY DESCRIPTION (Include Building Name, Number and Floor or Room Number)									
Building Name:									
Address: 2067 Bartow Avenue									
CI - B							7:n. 1047F		
20 Lillianderic valence in the exist of the ex-	. Lite Commence with		State. NT		Zip: 10475				
Site Location: Cellar	regions with the second		er symmet.		1 -1 11	1	411		
Building Size: 785,230 SF			# of Floo		Age in Years: 47				
Present Use: Commercial			Prior Use	: Commercial					
Decodure Technics Analytics									
Procedure, Including Analytical Method, If Appropriate, Used to Detect the Presence of Asbestos Material: PLM — Polarized Light Microscopy									
Approximate amount of asbes	tos , R. AC	M	Non Eriphia						
Including	to be		Non-Friable		Indicate Unit of Measurement				
Regulated ACM to be rem			Asbestos Material not to be removed		Below				
2. Category I ACM not remo		Cu	not to be	removed					
3. Category II ACM not remo				1.6					
*	3704		CAT I	CAT II			UNIT		
. Att.				G () 22		,	ONT		
					Linear Fee	et:	Ln M:		
Surface Area: Lay-in Ceiling T	ile, VAT & 2,06	5			Square Fe	et: X	Square Meter:		
Mastic						1	er a constant		
Volume RACM off Facility Com					CuFt:	1	Cu M:		
Scheduled Dates Asbestos Removal (mm/dd./yy)			Start: 04/25/2016		Complete: 04/01/2017				
Scheduled Dates Demo/Renovation (mm/dd./yy)			Start:		Complete:				

DESCRIPTION OF DIAMNED DEMOLITION OF RENOVATION	N WORK AND METHOD (S) TO BE LISED						
DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD (S) TO BE USED:							
DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION AND RENOVATION SITE:							
HEPA Vacs, Micro Traps (Negative Air Pressure) and amended water will be utilized for emissions control.							
WASTE TRANSPORTER #1							
Name: Tri State Transfer Associates							
Address: 1199 Randall Avenue							
	State: NY	Zip: 10474					
City: Long Island City Contact Name: Jimmy Byrne	State. NT	Telephone: 718-617-0771					
WASTE TRANSPORTER #2							
Name: ATC Address: 2 Moriches Middle Island Road							
City: Shirley	State: NY	Zip:					
- 10 M H J A J 10 C M H J 10 M J	State. N1	Telephone: 631-924-5050					
WASTE TRANSPORTER #3							
	nmontal Candicas						
Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services							
Location: 11-02 Queens Plaza South City: Long Island City	City: Long Island City	City Long Taland City					
Telephone: 718-349-0900	City: Long Island City	City: Long Island City					
Disposal Facility							
Name: Minerva Enterprises Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE							
	Location: 9000 Minerva Road, SE						
	ite: On	Zip: 44688					
FOR EMERGENCY RENOVATIONS							
Date and Hour of Emergency (mm/dd./yy)							
Description of the Sudden, Unexpected Event:		11.6					
Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:							
DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY							
NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered							
unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA							
Vacs, to be put in 6 mil poly bags for proper disposal.							
I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY							
THIS PERSON WILL BE AVAILABLE FOR INSPECTION DUR	ING NORMAL BUSINESS HOURS (require	d I year arter promulgation)					
04/14/2016							
Signature of Avner/Operator Date							
I certify that the above information is correct							
1 Certify that above information is correct							
04/14/2016							
Signature of Owner/Operator Date							
(V ' '							

Chi n